ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

**BBMP ENGINEERING DEPARTMENT**

**Road History Data Sheet**

## General

| Zone | Ward No. | Ward Name |
|---|---|---|
| DASARAHALLI | 12 | Shettihalli |
| **Street ID** | **Street Name** | **Significant Landmark** |
| W1055, W1061, W1057, W1063, W0798, W1059 | NA, 3rd Crs, 2nd Crs | Shettyhalli main road |
| **Segment No.** | **Total Length (m)** | |
| 12/C-W1055/S033359 | 76.86 | |

**Segment Details**

| Seg No. | Length (m) | Start Coordinates | | End Coordinates | | From | To |
|---|---|---|---|---|---|---|---|
| 1 | 76.86 | 77.516332 | 13.064656 | 77.517039 | 13.064708 | W1075 | W1075 |

## Work Details

**History of Road / Lane / Circles**

| Name of the Work | Sanctioned Estimated Amount (Rs.) | Sanctioned Year |
|---|---|---|
| Maintenance of roads and footpath in ward no.12 Shettyhalli | 2000000 | 2020 |
| **Year** | **Type of Work** | **Other Work Type** |
| 2020 - 2021 | Others | |
| **Tender** | **Work Details** | **Job No. / Work Code** |
| Tender | | 012-20-000076 |
| **Work Order No.** | **Work Order Date** | **Period of Extention** |
| EE/DD/WO/163/2020-21 | 20/01/2021 | |
| **Defect Liability Period From** | **Defect Liability Period To** | **Multiple road involved with the same Job No/ Work Code #** |
| 15/03/2021 | 15/03/2022 | No |

## Contractor Details

| Name of Contractor | Contractor Reg No (BBMP/PWD) | Expenditure Booked \ Released (Rs) |
|---|---|---|
| Manikanta V | | 1497113.00 |
| **Phone No.** | **E-Mail ID** | |
| 9008007218 | | |

**Zone:** DASARAHALLI **Ward No:** 12 **Ward Name:** Shettihalli **Street ID:** W1055, W1061, W1057, W1063,

Scanned by CamScanner

## Field Inspection Details

| Number of Trees | Any Other Information | Name |
|---|---|---|
| 0 | | Maintainance of roads and footpath in wardno 12 She |

| Date of Inspection | Remarks |
|---|---|
| 08/04/2021 | |

| Category | Image | Photo Remark |
|---|---|---|
| Drain Condition | | This photo seems out of range. |
| Footpath Condition | | This photo seems out of range. |
| Road Condition | | This photo seems out of range. |
| Segment End | | This photo seems out of range. |
| Segment Start | | This photo seems out of range. |

## Remarks

| Designation | Approver Name | Date | Target Date | Remark |
|---|---|---|---|---|
| CE | CE DAS | 27/04/2021 | 08/05/2021 | APPROVED |
| E | EE DAS | 27/04/2021 | 08/05/2021 | Completed |
| EE | M Nagesh Murthy | 08/04/2021 | 08/05/2021 | approved |
| | A.P. Shivakumar | 08/04/2021 | 08/05/2021 | approved |
| | A.P. Shivakumar | 08/04/2021 | 08/05/2021 | approved |

DASARAHALLI **Ward No:** 12 **Ward Name:** Shettihalli **Street ID:** W1055, W1061, W1057, W1063,

Scanned by CamScanner

Bruhat Bangalore Mahanagara Palike

**BBMP ENGINEERING DEPARTMENT**

**Road History Data Sheet**

## General

| Zone | Ward No. | Ward Name |
|---|---|---|
| DASARAHALLI | 12 | Shettihalli |
| **Street ID** | **Street Name** | **Significant Landmark** |
| W1055, W1061, W1057, W1063, W0798, W1059 | NA, 3rd Crs, 2nd Crs | Shettyhalli main road |
| **Segment No.** | **Total Length (m)** | |
| 12/C-W1055/S033359 | 76.86 (936m²) | |

**Segment Details**

| Seg No. | Length (m) | Start Coordinates | | End Coordinates | | From | To |
|---|---|---|---|---|---|---|---|
| 1 | 76.86 | 77.516332 | 13.064656 | 77.517039 | 13.064708 | W1075 | W1075 |

## Work Details

History of Road / Lane / Circles

| Name of the Work | Sanctioned Estimated Amount (Rs.) | Sanctioned Year |
|---|---|---|
| Maintenance of roads and footpath in ward no.12 Shettyhalli | 2000000 | 2020 |
| **Year** | **Type of Work** | **Other Work Type** |
| 2020 - 2021 | Others | |
| **Tender** | **Work Details** | **Job No. / Work Code** |
| Tender | | 012-20-000076 |
| **Work Order No.** | **Work Order Date** | **Period of Extention** |
| EE/DD/WO/163/2020-21 | 20/01/2021 | |
| **Defect Liability Period From** | **Defect Liability Period To** | **Multiple road involved with the same Job No/ Work Code #** |
| 15/03/2021 | 15/03/2022 | No |

## Contractor Details

| Name of Contractor | Contractor Reg No (BBMP/PWD) | Expenditure Booked \ Released (Rs) |
|---|---|---|
| Manikanta V | | 1497113.00 |
| **Phone No.** | **E-Mail ID** | |
| 9008007218 | | |

**Zone:** DASARAHALLI **Ward No:** 12 **Ward Name:** Shettihalli **Street ID:** W1055, W1061, W1057, W1063,

Scanned by CamScanner

## Field Inspection Details

**Number of Trees**

0

**Any Other Information**

**Name**

Maintanance of roads and footpath in wardno 12 She

**Date of Inspection**

08/04/2021

**Remarks**

| Category | Image | Photo Remark |
|---|---|---|
| Drain Condition | | This photo seems out of range. |
| Footpath Condition | | This photo seems out of range. |
| Road Condition | | This photo seems out of range. |
| Segment End | | This photo seems out of range. |
| Segment Start | | This photo seems out of range. |

## Remarks

| Designation | Approver Name | Date | Target Date | Remark |
|---|---|---|---|---|

**Zone:** DASARAHALLI **Ward No:** 12 **Ward Name:** Shettihalli **Street ID:** W1055, W1061, W1057, W1063,

Scanned by CamScanner